

# Meaning of Quality


- Webster's Dictionary
  - degree of excellence of a thing
- American Society for Quality
  - totality of features and characteristics that satisfy needs
- Consumer's and producer's perspective



## History (Cont..)

<http://www.deming.org/deminghtml/wedi.html>

- ◆ 1950's: Deming and Juran's introduction to Japan of Statistical Quality Control Techniques



<http://www.juran.com/drjuran.html>

## More quality gurus

<b>Philip Crosby</b>	<b>Quality is free - the optimum is zero defects.</b>
<b>W. Edwards Deming</b>	<b>Deming's 14 points. How to use statistics.</b>
<b>Armand Feigenbaum</b>	<b>Total quality control.</b>
<b>Kaoru Ishikawa</b>	<b>Quality circles and cause and effect diagrams</b>
<b>Joseph Juran</b>	<b>Quality as fitness for use, rather than conformance to specification.</b>
<b>Genichi Taguchi</b>	<b>Loss function. Minimize variation.</b>

## Historie řízení jakosti a ISO 9000

- 1900** Výrobová normalizace, vojenský průmysl
- 1920** Organizovaná kontrola, členění kontroly na vstupní, mezioperační a výstupní
- 1930** Shewart vytváří principy řízení kvality, regulace procesů pomocí SPC
- 1940** Kontrola pomocí zkušebních nástrojů, kontrola výrobních prostředků, plánování kontroly, určování příčin a následků
- 1950** Japonský průmysl se snaží v kvalitě výrobků dostihnout USA pomocí nových metod řízení kvality procesů
- 1970** Integrované zabezpečování kvality, zabezpečování kvality nejen ve výrobě ale i ve vývoji a přípravě výroby, analýza plánů konstrukce, testů, nedostatků, reklamací, certifikace výrobků
- 1979** Vydání normy BS 5750 (vzorem byly vojenské normy AQAP-1, 4 a 9) - 3.části (1.specifikace systému kvality 2.-3.specifikace kontrolního systému)
- 1987** Organizace ISO vydává poprvé normy ISO řady 9000
- 1994** První revize norem řady ISO 9000
- 2000** Druhá „velká“ revize norem řady ISO 9000


# Quality Gurus

- ◆ Walter Shewart
  - In 1920s, developed control charts
  - Introduced term “*quality assurance*”
- ◆ W. Edwards Deming
  - Developed courses during World War II to teach statistical quality-control techniques to engineers and executives of companies that were military suppliers
  - After war, began teaching statistical quality control to Japanese companies
- ◆ Joseph M. Juran
  - Followed Deming to Japan in 1954
  - Focused on strategic quality planning

# Quality Gurus (cont.)

- **Armand V. Feigenbaum**
  - In 1951, introduced concepts of total quality control and continuous quality improvement
- **Philip Crosby**
  - In 1979, emphasized that costs of poor quality far outweigh cost of preventing poor quality
  - In 1984, defined absolutes of quality management—conformance to requirements, prevention, and “zero defects”
- **Kaoru Ishikawa**
  - Promoted use of quality circles
  - Developed “fishbone” diagram
  - Emphasized importance of internal customer

# Deming Wheel: PDCA Cycle



Jestliže jsou požadavky kapitoly „Odpovědnost managementu“ realizovány v praxi, dochází k plánování zdrojů a prostředků organizace (**Plan**).


Splnění požadavků z kapitoly „Řízení zdrojů“ zajišťuje, že „realizace produktu a/nebo služby“ může proběhnout efektivně a účinně (**Do**).

Výsledkem realizace produktu jsou produkty a služby. Výkon procesů a kvalita produktu jsou při tom průběžně měřeny (**Check**).

Požadavky kapitoly „Měření, analýza a zlepšení“ se cyklus k „Odpovědnosti managementu“ opět uzavírá (**Act**).



# Meaning of Quality



# Total Quality Management

- ◆ Commitment to quality throughout organization

- ◆ **Principles of TQM**

- Customer-oriented
- Leadership
- Strategic planning
- Employee responsibility
- Continuous improvement
- Cooperation
- Statistical methods
- Training and education

# Basic Economic Quality Level Model



## **Princip 1 – Orientace na zákazníka**

Organizace závisí na svých zákaznících, a proto mají porozumět současných i budoucím potřebám zákazníků, splňovat jejich požadavky a snažit se překonat jejich očekávání.

## **Princip 2 – Vedení**

Vedoucí pracovníci vytvářejí shodu účelu a zaměření organizace. Mají vytvářet a zachovávat interní prostředí, v kterém se lidé mohou zcela zasazovat za dosažení cílů organizace.

## **Princip 3 – Zapojení osob**

Na všech úrovních určují lidé charakter organizace a jejich úplné zapojení umožňuje nasadit své schopnosti k užitku organizace.

## **Princip 4 – Procesně orientovaný koncept**

Požadovaného výsledku lze dosáhnout efektivněji tehdy, když jsou činnosti a příslušné zdroje vedeny a řízeny jako proces.

## **Princip 5 – Systémově orientovaný koncept řízení**

Identifikace, pochopení, vedení a řízení procesů, které jsou vzájemně propojeny jako systém, přispívá k účinnosti a efektivitě organizace při dosahování svých cílů.

## **Princip 6 – Neustálé zlepšování**

Neustálé zlepšování celkového výkonu organizace představuje trvalý cíl organizace.


## **Princip 7 – Věcný koncept pro rozhodování**

Účinná rozhodnutí se zakládají na analýze dat a informací.

## **Princip 8 – Dodavatelské vztahy k vzájemnému užítku**

Organizace a její dodavatelé jsou na sobě závislí. Vztahy sloužící k vzájemnému užítku zvyšují schopnost tvorby hodnot obou stran.


## Neustálé zlepšování systému managementu jakosti



Legenda:

- > Činnost přidávající hodnotu
- .....> Informační tok

POZNÁMKA: Text v závorkách neplatí pro ISO 9001  
Model procesně orientovaného systému managementu jakosti



**Model excellence EFQM**



# TQM and...


- ◆ **... Partnering**
  - a relationship between a company and its supplier based on mutual quality standards
- ◆ **... Customers**
  - system must measure customer satisfaction
- ◆ **... Information Technology**
  - infrastructure of hardware, networks, and software necessary to support a quality program

# Quality Improvement and Role of Employees

- ◆ **Participative problem solving**
  - employees involved in quality management
  - every employee has undergone extensive training to provide quality service to Disney's guests



# Quality Circle




# TQM in Service Companies

- ◆ **Principles of TQM apply equally well to services and manufacturing**
- ◆ **Services and manufacturing companies have similar inputs but different processes and outputs**
- ◆ **Services tend to be labor intensive**
- ◆ **Service defects are not always easy to measure because service output is not usually a tangible item**

# Cost of Quality

- ◆ **Cost of Achieving Good Quality**
  - **Prevention costs**
    - costs incurred during product design
  - **Appraisal costs**
    - costs of measuring, testing, and analyzing
- ◆ **Cost of Poor Quality**
  - **Internal failure costs**
    - include scrap, rework, process failure, downtime, and price reductions
  - **External failure costs**
    - include complaints, returns, warranty claims, liability, and lost sales

# Juran, J.M., "Planning for Quality"



# Prevention Costs

- ◆ **Quality planning costs**
  - costs of developing and implementing quality management program
- ◆ **Product-design costs**
  - costs of designing products with quality characteristics
- ◆ **Process costs**
  - costs expended to make sure productive process conforms to quality specifications
- ◆ **Training costs**
  - costs of developing and putting on quality training programs for employees and management
- ◆ **Information costs**
  - costs of acquiring and maintaining data related to quality, and development of reports on quality performance

# Appraisal Costs

- ◆ Inspection and testing
  - costs of testing and inspecting materials, parts, and product at various stages and at end of process
- ◆ Test equipment costs
  - costs of maintaining equipment used in testing quality characteristics of products
- ◆ Operator costs
  - costs of time spent by operators to gather data for testing product quality, to make equipment adjustments to maintain quality, and to stop work to assess quality



# Internal Failure Costs

- ◆ *Scrap costs*
  - costs of poor-quality products that must be discarded, including labor, material, and indirect costs
- ◆ *Rework costs*
  - costs of fixing defective products to conform to quality specifications
- ◆ *Process failure costs*
  - costs of determining why production process is producing poor-quality products
- ◆ *Process downtime costs*
  - costs of shutting down productive process to fix problem
- ◆ *Price-downgrading costs*
  - costs of discounting poor-quality products—that is, selling products as “seconds”


# External Failure Costs

- ◆ **Customer complaint costs**
  - costs of investigating and satisfactorily responding to a customer complaint resulting from a poor-quality product
- ◆ **Product return costs**
  - costs of handling and replacing poor-quality products returned by customer
- ◆ **Warranty claims costs**
  - costs of complying with product warranties
- ◆ **Product liability costs**
  - litigation costs resulting from product liability and customer injury
- ◆ **Lost sales costs**
  - costs incurred because customers are dissatisfied with poor quality products and do not make additional purchases





# Measuring and Reporting Quality Costs

## ◆ Index numbers


- ratios that measure quality costs against a base value
- **labor index**
  - ratio of quality cost to labor hours
- **cost index**
  - ratio of quality cost to manufacturing cost
- **sales index**
  - ratio of quality cost to sales
- **production index**
  - ratio of quality cost to units of final product




# Možné struktury nákladů v modelu PAF



# Trendy v modelu PAF



# Grafické znázornění monitorování nákladů na proces




# Seven Quality Control Tools

- ◆ Pareto Analysis
- ◆ Flow Chart
- ◆ Check Sheet
- ◆ Histogram
- ◆ Scatter Diagram
- ◆ SPC Chart
- ◆ Cause-and-Effect Diagram




# Pareto Analysis

<b>CAUSE</b>	<b>NUMBER OF DEFECTS</b>	<b>PERCENTAGE</b>
<b>Poor design</b>	<b>80</b>	<b>64 %</b>
<b>Wrong part dimensions</b>	<b>16</b>	<b>13</b>
<b>Defective parts</b>	<b>12</b>	<b>10</b>
<b>Incorrect machine calibration</b>	<b>7</b>	<b>6</b>
<b>Operator errors</b>	<b>4</b>	<b>3</b>
<b>Defective material</b>	<b>3</b>	<b>2</b>
<b>Surface abrasions</b>	<b>3</b>	<b>2</b>
	<b>125</b>	<b>100 %</b>



# Flow Chart



# Check Sheet

COMPONENTS REPLACED BY LAB

TIME PERIOD: 22 Feb to 27 Feb 2002

REPAIR TECHNICIAN: Bob

TV SET MODEL 1013

Integrated Circuits

||||

Capacitors

|||| ||| ||| ||| ||| ||

Resistors

||

Transformers


||||

Commands


CRT

|


# Histogram




# Scatter Diagram



# Control Chart



# Cause-and-Effect Diagram





# Baldrige Award

- ◆ Created in 1987 to stimulate growth of quality management in United States
- ◆ Categories
  - Leadership
  - Information and analysis
  - Strategic planning
  - Human resource
  - Focus
  - Process management
  - Business results
  - Customer and market focus

# Other Awards for Quality

## ◆ National individual awards

- Armand V. Feigenbaum Medal
- Deming Medal
- E. Jack Lancaster Medal
- Edwards Medal
- Shewart Medal
- Ishikawa Medal

## ◆ International awards

- European Quality Award
- Canadian Quality Award
- Australian Business Excellence Award
- Deming Prize from Japans

# American Customer Satisfaction Index (ACSI)

- ◆ Measures customer satisfaction
- ◆ Established in 1994
- ◆ Web site: [www.acsi.org](http://www.acsi.org)
  - Examples (in 2003)
    - Amazon.com scored 88 (highest in service)
    - Dell scored of 78 (highest in computer industry)
    - Cadillac scored 87 (highest in car industry)

# ISO 9000

- ◆ A set of procedures and policies for international quality certification of suppliers
- ◆ Standards
  - ISO 9000:2000
    - *Quality Management Systems—Fundamentals and Vocabulary*
    - defines fundamental terms and definitions used in ISO 9000 family
- ◆ ISO 9001:2000
  - *Quality Management Systems—Requirements*
  - standard to assess ability to achieve customer satisfaction
- ◆ ISO 9004:2000
  - *Quality Management Systems—Guidelines for Performance Improvements*
  - guidance to a company for continual improvement of its quality-management system

# Implications of ISO 9000 for U.S. Companies

- ◆ Many overseas companies will not do business with a supplier unless it has ISO 9000 certification
- ◆ ISO 9000 accreditation
- ◆ ISO registrars
- ◆ A total commitment to quality is required throughout an organization





# Chapter 4

## *Statistical Process Control*


***Operations Management - 5<sup>th</sup> Edition***

**Roberta Russell & Bernard W. Taylor, III**



# Basics of Statistical Process Control

- ◆ **Statistical Process Control (SPC)**
  - monitoring production process to detect and prevent poor quality
- ◆ **Sample**
  - subset of items produced to use for inspection
- ◆ **Control Charts**
  - process is within statistical control limits



# Variability

## ◆ Random

- common causes
- inherent in a process
- can be eliminated only through improvements in the system

## ◆ Non-Random

- special causes
- due to identifiable factors
- can be modified through operator or management action



# SPC in TQM

## ◆ SPC

- tool for identifying problems and make improvements
- contributes to the TQM goal of continuous improvements

# Quality Measures

## ◆ Attribute

- a product characteristic that can be evaluated with a discrete response
- good – bad; yes - no

## ◆ Variable

- a product characteristic that is continuous and can be measured
- weight - length

# Applying SPC to Service

- ◆ Nature of defect is different in services
- ◆ Service defect is a failure to meet customer requirements
- ◆ Monitor times, customer satisfaction

# Applying SPC to Service (cont.)

- ◆ Hospitals
  - timeliness and quickness of care, staff responses to requests, accuracy of lab tests, cleanliness, courtesy, accuracy of paperwork, speed of admittance and checkouts
- ◆ Grocery stores
  - waiting time to check out, frequency of out-of-stock items, quality of food items, cleanliness, customer complaints, checkout register errors
- ◆ Airlines
  - flight delays, lost luggage and luggage handling, waiting time at ticket counters and check-in, agent and flight attendant courtesy, accurate flight information, passenger cabin cleanliness and maintenance

# Applying SPC to Service (cont.)

- ◆ Fast-food restaurants
  - waiting time for service, customer complaints, cleanliness, food quality, order accuracy, employee courtesy
- ◆ Catalogue-order companies
  - order accuracy, operator knowledge and courtesy, packaging, delivery time, phone order waiting time
- ◆ Insurance companies
  - billing accuracy, timeliness of claims processing, agent availability and response time


# Where to Use Control Charts

- ◆ Process has a tendency to go out of control
- ◆ Process is particularly harmful and costly if it goes out of control
- ◆ Examples
  - at the beginning of a process because it is a waste of time and money to begin production process with bad supplies
  - before a costly or irreversible point, after which product is difficult to rework or correct
  - before and after assembly or painting operations that might cover defects
  - before the outgoing final product or service is delivered

# Control Charts


- ◆ A graph that establishes control limits of a process
- ◆ Control limits
  - upper and lower bands of a control chart
- ◆ Types of charts
  - Attributes
    - p-chart
    - c-chart
  - Variables
    - range (R-chart)
    - mean ( $\bar{x}$  – chart)

# Process Control Chart





# Normal Distribution



# A Process Is in Control If ...

1. ... no sample points outside limits
2. ... most points near process average
3. ... about equal number of points above and below centerline
4. ... points appear randomly distributed

# Control Charts for Attributes

- p-charts
  - uses portion defective in a sample
- c-charts
  - uses number of defects in an item

# p-Chart

$$UCL = p + z\sigma_p$$

$$LCL = p - z\sigma_p$$

**$z$  = number of standard deviations from process average**

**$\bar{p}$  = sample proportion defective; an estimate of process average**

**$\sigma_p$  = standard deviation of sample proportion**

$$\sigma_p = \sqrt{\frac{\bar{p}(1 - \bar{p})}{n}}$$

# p-Chart Example

<b>SAMPLE</b>	<b>NUMBER OF DEFECTIVES</b>	<b>PROPORTION DEFECTIVE</b>
1	6	.06
2	0	.00
3	4	.04
:	:	:
:	:	:
20	<u>18</u>	.18
	200	

**20 samples of 100 pairs of jeans**

# p-Chart Example (cont.)

$$\bar{p} = \frac{\text{total defectives}}{\text{total sample observations}} = 200 / 20(100) = 0.10$$


$$\text{UCL} = \bar{p} + z \sqrt{\frac{\bar{p}(1 - \bar{p})}{n}} = 0.10 + 3 \sqrt{\frac{0.10(1 - 0.10)}{100}}$$

$$\text{UCL} = 0.190$$

$$\text{LCL} = \bar{p} - z \sqrt{\frac{\bar{p}(1 - \bar{p})}{n}} = 0.10 - 3 \sqrt{\frac{0.10(1 - 0.10)}{100}}$$

$$\text{LCL} = 0.010$$

# p-Chart Example (cont.)



# c-Chart

$$UCL = \bar{c} + z\sigma_c$$

$$LCL = \bar{c} - z\sigma_c$$

$$\sigma_c = \sqrt{\bar{c}}$$

where

**c = number of defects per sample**



# c-Chart (cont.)

Number of defects in 15 sample rooms


SAMPLE	NUMBER OF DEFECTS
1	12
2	8
3	16
:	:
:	:
15	<u>15</u> 190

$$\bar{c} = \frac{190}{15} = 12.67$$

$$\begin{aligned} \text{UCL} &= \bar{c} + z\sigma_c \\ &= 12.67 + 3\sqrt{12.67} \\ &= 23.35 \end{aligned}$$

$$\begin{aligned} \text{LCL} &= \bar{c} - z\sigma_c \\ &= 12.67 - 3\sqrt{12.67} \\ &= 1.99 \end{aligned}$$

# c-Chart (cont.)



# Control Charts for Variables

- Mean chart (  $\bar{x}$ -Chart )
  - uses average of a sample
- Range chart ( R-Chart )
  - uses amount of dispersion in a sample

# x-bar Chart

$$\bar{\bar{x}} = \frac{\bar{x}_1 + \bar{x}_2 + \dots + \bar{x}_k}{k}$$

$$\text{UCL} = \bar{\bar{x}} + A_2\bar{R} \quad \text{LCL} = \bar{\bar{x}} - A_2\bar{R}$$

where

$\bar{\bar{x}}$  = average of sample means

# x-bar Chart Example

SAMPLE $k$	OBSERVATIONS (SLIP- RING DIAMETER, CM)					$\bar{x}$	$R$
	1	2	3	4	5		
1	5.02	5.01	4.94	4.99	4.96	4.98	0.08
2	5.01	5.03	5.07	4.95	4.96	5.00	0.12
3	4.99	5.00	4.93	4.92	4.99	4.97	0.08
4	5.03	4.91	5.01	4.98	4.89	4.96	0.14
5	4.95	4.92	5.03	5.05	5.01	4.99	0.13
6	4.97	5.06	5.06	4.96	5.03	5.01	0.10
7	5.05	5.01	5.10	4.96	4.99	5.02	0.14
8	5.09	5.10	5.00	4.99	5.08	5.05	0.11
9	5.14	5.10	4.99	5.08	5.09	5.08	0.15
10	5.01	4.98	5.08	5.07	4.99	5.03	0.10
						<u>50.09</u>	<u>1.15</u>

Example 15.4

# x-bar Chart Example (cont.)


$$\bar{\bar{x}} = \frac{\sum \bar{x}}{k} = \frac{50.09}{10} = 5.01 \text{ cm}$$

$$\text{UCL} = \bar{\bar{x}} + A_2 \bar{R} = 5.01 + (0.58)(0.115) = 5.08$$

$$\text{LCL} = \bar{\bar{x}} - A_2 \bar{R} = 5.01 - (0.58)(0.115) = 4.94$$

Retrieve Factor Value  $A_2$

x-bar  
Chart  
Example  
(cont.)



# R- Chart

$$UCL = D_4 \bar{R} \qquad LCL = D_3 \bar{R}$$

$$\bar{R} = \frac{\sum R}{k}$$

where

$\bar{R}$  = range of each sample

$k$  = number of samples



# R-Chart Example

SAMPLE $k$	OBSERVATIONS (SLIP-RING DIAMETER, CM)					$\bar{x}$	$R$
	1	2	3	4	5		
1	5.02	5.01	4.94	4.99	4.96	4.98	0.08
2	5.01	5.03	5.07	4.95	4.96	5.00	0.12
3	4.99	5.00	4.93	4.92	4.99	4.97	0.08
4	5.03	4.91	5.01	4.98	4.89	4.96	0.14
5	4.95	4.92	5.03	5.05	5.01	4.99	0.13
6	4.97	5.06	5.06	4.96	5.03	5.01	0.10
7	5.05	5.01	5.10	4.96	4.99	5.02	0.14
8	5.09	5.10	5.00	4.99	5.08	5.05	0.11
9	5.14	5.10	4.99	5.08	5.09	5.08	0.15
10	5.01	4.98	5.08	5.07	4.99	5.03	0.10
						<u>50.09</u>	<u>1.15</u>

Example 15.3

# R-Chart Example (cont.)


$$\bar{R} = \frac{\sum R}{k} = \frac{1.15}{10} = 0.115$$

$$UCL = D_4 \bar{R} = 2.11(0.115) = 0.243$$

$$LCL = D_3 \bar{R} = 0(0.115) = 0$$

Retrieve Factor Values  $D_3$  and  $D_4$


# R-Chart Example (cont.)




# Using $\bar{x}$ and R-Charts Together

- Process average and process variability must be in control
- It is possible for samples to have very narrow ranges, but their averages is beyond control limits
- It is possible for sample averages to be in control, but ranges might be very large

# Control Chart Patterns




**Sample observations  
consistently below the  
center line**




**Sample observations  
consistently above the  
center line**

# Control Chart Patterns (cont.)



**Sample observations  
consistently increasing**




**Sample observations  
consistently decreasing**



# Sample Size


- **Attribute charts require larger sample sizes**
  - 50 to 100 parts in a sample
- **Variable charts require smaller samples**
  - 2 to 10 parts in a sample

# SPC with Excel





# SPC with Excel: Formulas




# Process Capability


- ◆ Tolerances
  - design specifications reflecting product requirements
- ◆ Process capability
  - range of natural variability in a process what we measure with control charts

# Process Capability

(a) Natural variation exceeds design specifications; process is not capable of meeting specifications all the time.




(b) Design specifications and natural variation the same; process is capable of meeting specifications most of the time.




# Process Capability (cont.)

(c) Design specifications greater than natural variation; process is capable of always conforming to specifications.



(d) Specifications greater than natural variation, but process off center; capable but some output will not meet upper specification.



# Process Capability Measures

## Process Capability Ratio

$$C_p = \frac{\text{tolerance range}}{\text{process range}}$$

$$= \frac{\text{upper specification limit} - \text{lower specification limit}}{6\sigma}$$

# Computing $C_p$

Net weight specification = 9.0 oz  $\pm$  0.5 oz

Process mean = 8.80 oz

Process standard deviation = 0.12 oz

$$C_p = \frac{\text{upper specification limit} - \text{lower specification limit}}{6\sigma}$$
$$= \frac{9.5 - 8.5}{6(0.12)} = 1.39$$

# Process Capability Measures

## *Process Capability Index*

$$C_{pk} = \text{minimum} \left[ \frac{\bar{\bar{x}} - \text{lower specification limit}}{3\sigma}, \frac{\text{upper specification limit} - \bar{\bar{x}}}{3\sigma} \right]$$

# Computing $C_{pk}$

Net weight specification = 9.0 oz  $\pm$  0.5 oz

Process mean = 8.80 oz

Process standard deviation = 0.12 oz

$$C_{pk} = \text{minimum} \left[ \frac{\bar{x} - \text{lower specification limit}}{3\sigma}, \frac{\text{upper specification limit} - \bar{x}}{3\sigma} \right]$$

$$= \text{minimum} \left[ \frac{8.80 - 8.50}{3(0.12)}, \frac{9.50 - 8.80}{3(0.12)} \right] = 0.83$$




## Appendix:

### Determining Control Limits for $\bar{x}$ -bar and $R$ -Charts

SAMPLE SIZE $n$	FACTOR FOR $\bar{x}$ -CHART $A_2$	FACTORS FOR $R$ -CHART	
		$D_3$	$D_4$
2	1.88	0.00	3.27
3	1.02	0.00	2.57
4	0.73	0.00	2.28
5	0.58	0.00	2.11
6	0.48	0.00	2.00
7	0.42	0.08	1.92
8	0.37	0.14	1.86
9	0.44	0.18	1.82
10	0.11	0.22	1.78
11	0.99	0.26	1.74
12	0.77	0.28	1.72
13	0.55	0.31	1.69
14	0.44	0.33	1.67
15	0.22	0.35	1.65
16	0.11	0.36	1.64
17	0.00	0.38	1.62
18	0.99	0.39	1.61
19	0.99	0.40	1.61
20	0.88	0.41	1.59

Return



Copyright 2006 John Wiley & Sons, Inc.  
All rights reserved. Reproduction or translation of this work beyond that permitted in section 117 of the 1976 United States Copyright Act without express permission of the copyright owner is unlawful. Request for further information should be addressed to the Permission Department, John Wiley & Sons, Inc. The purchaser may make back-up copies for his/her own use only and not for distribution or resale. The Publisher assumes no responsibility for errors, omissions, or damages caused by the use of these programs or from the use of the information herein.