

J. Jeswiet lectures, 2005 edition.

The fine print


Powerpoint format lecture © J. Jeswiet 2005

The contents of this lecture are the sole copyright of J. Jeswiet,
Professor of Mechanical Engineering.

Use of the contents of this lecture without the written permission of the author is illegal.

Inquiries should be addressed to: J. Jeswiet, Mechanical Engineering, McLaughlin Hall,
Queen's University, Kingston, ON, Canada K7L 3N6
Fax: 613-533-6489
jeswiet@me.queensu.ca

Lecture 21



MANUFACTURING ENGINEERING
MECH 213

Topic:
STEEL II



G'day.

The last day we ended with definitions of the different carbon ranges for steels

Low carbon steel: 0.10 – 0.30 %C

Medium carbon steel: 0.30 – 0.85 %C

High carbon steel: 0.85 – 1.3 %C

Classification of Steels

- Various countries adopt their own standards for classifying steels
- In North America the four digit system of the AISI and SAE is used
- In the SAE and AISI methods of numbering


the first two numbers indicate the level of alloying

the last two digits indicate carbon content in hundredths of a percent by weight

1020
↖ ↗
low alloying 0.20 wt% C

Question:


What effect does increasing carbon content have upon strength?



Stress-strain diagrams for typical hot-worked iron-carbon alloys.



Now consider the Iron – Carbon Phase Diagram

- Austenite, γ , has a face-centred cubic, FCC, crystal structure.




useful allotropic forms of iron:

- Ferrite, α , has a body-centred cubic, BCC, structure.



The Eutectoid is very important in steel making



**Eutectoid,
Pearlite,
 $\alpha - \text{Fe}_3\text{C}$**




Low carbon steel: 0.10 – 0.30 %C
Medium carbon steel: 0.30 – 0.85 %C
High carbon steel: 0.85 – 1.3 %C

Schematic illustration of the microstructures for an iron-carbon alloy of eutectoid composition (0.77% carbon), above and below the eutectoid temperature of 727 °C (1341 °F).

Pearlite


Steel Crystal Structures

- Pearlite is made up of cementite (Fe_3C) lamellae, and ferrite (Fe).
- cementite is black and ferrite is white in this figure.
- 100% Pearlite occurs at the eutectoid. To the left of the eutectoid, ferrite increases and pearlite decreases
- To the right of the eutectoid, the amount of cementite increases




Low carbon steel: 0.10 – 0.30 %C
 Medium carbon steel: 0.30 – 0.85 %C
 High carbon steel: 0.85 – 1.3 %C

Observe what happens as carbon content increases:



Iron Carbon Diagram




Important types of Heat Treatment in Steel are:

- **Normalizing**
- **Annealing**
- **Full Anneal**
- **Process Anneal**
- **Spheroidizing Anneal**

See the appendix for today's lectures to see definitions.


Heat treating temperature ranges for plain carbon steels




Alloying has an effect upon the Eutectoid Temperature

and upon the carbon content


and upon the size of the austenitic zone



Effect of alloying elements in steel on the eutectoid temperature.





Effect of manganese on the austenite phase region.



Effect of elements on the carbon content of the eutectoid.

The rate of cooling can also have a large effect upon the microscopic structure of the steel


martensitic structure



Hardness of steels in the quenched and normalized conditions, as a function of carbon content.


Phase diagrams are equilibrium diagrams
& are derived by cooling slowly

- However, if the alloy is cooled at faster rates, different micro-structures and properties can be achieved
- Time, the rate at which cooling occurs, temperature of the solution and transformation are all inter-related
- This give us another diagram called the TTT diagram




Time Temperature Transformation

- The knee of the TTT diagram indicates where changes in microstructure begin to occur.
- If the temperature of the steel can be lowered quickly enough a change in microstructure can be avoided until it is desired; changes can be “frozen” for a while
- In general the faster the steel is quenched the harder it will become
- Because rapid cooling can cause thermal stresses (and cracking) a balance must be achieved between rapid cooling and stress relief




Steel Crystal Structures

- Martensite forms only when steel is quenched quickly enough to reach 225°C, without forming pearlite or bainite first.
- It is the hardest of all steel crystal structures.
- As-quenched it has very high strength, but has very low fracture resistance, or toughness.



This is what it looks like under 500X magnification


The TTT curves are also affected by the alloy content



Can see a tendency to retain austenite; which occurs in stainless steels


Schematic effect of nickel and chromium on the isothermal transformation diagram.

Quenching & Tempering; some strategies



Tempering


- This consists of reheating the steel to a given temperature to allow formation of one or a combination of the following:
 - cementite,
 - ferrite,
 - spheroidization [clustering of carbon atoms],
 - carbides in the case of alloying elements,
 - new microstructures (such as bainite or pearlite)
- The chief goal of tempering is to toughen the steel and decrease its brittleness
- a tempering stage is often applied in the case of martensitic steels




The End

Thank you for your attention

Two Alloys which are used for either increasing Hardenability or corrosion resistance or both, affect the austenitic zone as shown



Effect of chromium on the austenite phase region. (After Bain, Alloying Elements in Steel)



Effect of molybdenum on the austenite phase region. (After Bain, Alloying Elements in Steel)

Normalizing: Heating a steel part of heavy section to a temperature 100° C above the upper critical range and then cooled in still air

Normalizing plays an important role in grain size.

1st the grain size is controlled by the size of the Austenite grains, from which they form on cooling;

2nd when steel is heated to just above the upper critical the grain growth is primarily a function of temperature and time


Annealing: any any heating and cooling operation that is applied to induce softening

Full Anneal: steel is heated to 100°C above the upper critical

Process Anneal: steel is heated to a temperature just below the lower critical

Spheroidizing Anneal: Any process of heating and cooling that produces a round or globular form of carbide in steels

Atomic models of three steel structures



Examples of steels:

xx indicates the carbon content

- | | |
|---|--|
| 10xx Plain carbon | 5xxx Chromium |
| 11xx Free-cutting carbon | 5xxxx Chromium |
| 13xx Manganese (1.75%) | 61xx Chromium (0.80 or 0.95%),
vanadium (0.10 or 0.15%) |
| 2xxx Nickel (3.50 or 5.00%) | 86xx Nickel (0.55%), chromium
(0.50%), molybdenum (0.20%) |
| 31xx Nickel (1.25%), chromium
(0.65 or 0.80%) | 87xx Nickel (0.55%), chromium
(0.50%), molybdenum (0.25%) |
| 33xx Nickel (3.50%), chromium
(1.55%) | 92xx Silicon (2.00%), manganese
(0.85%) |
| 40xx Molybdenum (0.25%) | 93xx Nickel (3.25%), chromium
(1.20%), molybdenum (0.12%) |
| 41xx Molybdenum (0.20%), chro-
mium (0.95%) | 94xx Nickel (0.45%), chromium
(0.40%), molybdenum (0.12%) |
| 43xx Molybdenum (0.25%), chro-
mium (0.50 or 0.80%), nickel
(1.80%) | 97xx Nickel (0.55%), chromium
(0.17%), molybdenum (0.20%) |
| 46xx Molybdenum (0.25%), nickel
(1.80%) | 98xx Nickel (1.00%), chromium
(0.80%), molybdenum (0.25%) |
| 48xx Molybdenum (0.25%), nickel
(3.50%) | |



COMBINING TENDENCIES OF ELEMENTS IN ANNEALED STEEL.

Element	Dissolve in Ferrite	Dissolve in Austenite	Form Carbide	In Nonmetallic Inclusions	Form Special Intermetallic Compounds	In Elemental State
Nickel Silicon Aluminum Zirconium Phosphorus Sulfur Copper	<div> <div>Ni Si Al Zr P S Cu</div> <div>with → ease</div> </div>	Ni Si Al Zr P S Cu		$\text{SiO}_2 \cdot \text{Mn}_2\text{O}_3$ Al_2O_3 etc. ZrO $\{\text{MnFeS}$ ZrS	NiSi (?) Al_3N_4 Zr_3N_4	Cu when > ±0.8%
Manganese Chromium Tungsten Molybdenum Vanadium Titanium	<div> <div>Mn Cr W Mo V Ti</div> <div>time → and temp.</div> </div>	$\text{Mn} \rightleftharpoons$ $\text{Cr} \rightleftharpoons$ $\text{W} \rightleftharpoons$ $\text{Mo} \rightleftharpoons$ $\text{V} \rightleftharpoons$ $\text{Ti} \rightleftharpoons$	Mn Cr W Mo V Ti	$\{\text{MnS, MnFeO}$ $\text{MnO} \cdot \text{SiO}_2$ Cr_2O_3 V_2O_5 Ti_2O_3	V_3N_4 $\{\text{Ti}_3\text{N}_4, \text{C}$ Ti_3N_4	Pb (?)
Lead						
Principal effect:	Strengthen	Increase harden- ability	Reduce harden- ability Fine-grain Toughness	Deoxidizers and grain- growth con- trol	Increase hardness	Increase machin- ability