


Fázové diagramy binárních soustav



Odmísemí a spinodální rozpad





Fig. 1.30 The derivation of a phase diagram where $\Delta H_{\text{mix}}^S > \Delta H_{\text{mix}}^L = 0$. Free energy v. composition curves for (a) T_1 , (b) T_2 , and (c) T_3 .






Fig. 1.29 The derivation of a simple phase diagram from the free energy curves for the liquid (L) and solid (S).

Aktivita složek v binárních diagramech

$$a_A^\alpha = a_A^\beta, \quad a_B^\alpha = a_B^\beta$$

(1.47)




Fig. 1.28 The variation of a_A and a_B with composition for a binary system containing two ideal solutions, α and β .

Diskuse

[http://www.ironcarbon
diagram.com/product.
aspx?id=5](http://www.ironcarbondiagram.com/product.aspx?id=5)

